

FIG. 1

RECORDING SENSITIVITY OF THE RECORDING MATERIAL
CAUSING FOGGING AFTER TWO HOURS OF IRRADIATION
UNDER A WHITE FLUORESCENT LIGHT (mJ/cm^2)




FIG. 2

EMISSION DISTRIBUTION OF WHITE FLUORESCENT




FIG. 3




FIG. 4




FIG. 5 (a)




FIG. 5 (b)




FIG. 6

